

Deficiency Photo of the Year - 2021

Ship name:	OCEANA
IMO Number:	9634684
Flag:	Antigua and Barbuda
Call sign/MMSI	V2GK4/305969000
Ship type:	Container ship
Date keel laid:	07.04.2012
Gross tonnage:	17,769
Recognized organization:	DNV AS
ISM Company:	Leonhardt & Blumberg Shipmanagement
	GmbH & Co KG
	(IMO No. 5979428)
Port of inspection:	Shanghai, China
Date of inspection:	21.01.2021
Detention:	Yes*



 $^{^{\}star}$ Detention was warranted for reason of deficiencies of crew rest records, lashing materials, firefighting equipment and failure on ISM.

Nature of deficiency:

Hull damage impairing seaworthiness:
The hull of void space forward center and around bulbous bow broken with the hole approx. dimensions 4.5m horizontal and vertical 3.2m and the other spots damaged, which impairing seaworthiness.

Reason for winning the prize:
This photo shows the evidence of hull damage.

Photo of detainable deficiency:
No

Picture of the ship



Pictures of the same deficiency: Hull damage impairing seaworthiness



<u>Pictures of detainable deficiency: Five cleats for No.4 and No.5 cargo hold</u>
<a href="https://doi.org/10.2016/j.june.2016/j.j



<u>Pictures of detainable deficiency: Both the fire hydrants of spray fire protect</u> <u>for No.2 cargo hold are unable to connect with the fire hose due to serious corrosion</u>






<u>Pictures of other deficiency: The steering gear was unable to operate from bridge due to failure</u>





Pictures of other deficiency: Defective fixed fire extinguishing installation





Picture of other deficiency: The designed crew not familiar with the wearing of fireman outfit



<u>Picture of other deficiency: The air pressure of the air cylinder for oil tank</u> <u>quick-closing valves low</u>



Picture of other deficiency: The lower light of starboard side light unlit



Picture of other deficiency: Pipe for boiler feed water system temporarily repaired with nylon block, and the heat insulation material missing



<u>Pictures of other deficiency: Cables of main engine control unit nearby M/E scavenging box accumulated by oil</u>





Picture of other deficiency: The key engineers not familiar with the testing of the chemical pumps for sewage treatment plant

