



Deficiency Photo of the Year – 2009

Ship name:	YING SHUN
IMO Number:	7507291
Flag:	Panama
Call sign/MMSI	3ECS8/371453000
Ship type:	Bulk carrier
Date keel laid:	1977
Gross tonnage:	21,952
Recognized organization:	Isthmus Bureau of Shipping, S.A.
ISM Company:	EVER GAIN SHIPPING SA (IMO No.5339822)
Port of inspection:	Vanino, Russian Federation
Date of inspection:	22.10.2009
Detention:	Yes*



Nature of deficiency:	Working conditions: Accident prevention-Accommodation ladder in poor condition.
Reason for winning the prize:	This photo demonstrates the unsafe stowage of the gangway ladder which would endanger the safe access to the vessel.
Photo of detainable deficiency:	No

* Detention was warranted for reason of deficiencies of overdue bottom survey, corrosion of lifeboat rudder and corrosion of securing devices for lifeboat lashing.

Picture of the ship



Picture of other deficiency: Bad condition of mooring rope.



apcis.tmoou.org

Picture of other deficiency: LIFEBOATS (P.S., STB.S.) - SCATES ARE MISSING



Picture of other deficiency: LAUNCHING INSTRUCTIONS FOR LIFEBOAT ARE UNREADABLE



Picture of other deficiency: LIFEBOAT (P.S.) - RUDDER IS CORRODED AND HAS HOLES DUE TO CORROSION (Detainable item)



Pictures of other deficiency: SECURING DEVICES FOR LASHINGS OF LIFEBOATS (P.S.), (STB.S.) ARE HEAVILY CORRODED (Detainable item)



Picture of other deficiency: STOWAGE OF LIFERAFT (P.S.) - WEAK LINK IS MISSING



Pictures of other deficiency: LIFEJACKETS FOR LIFERAFT ON FORECASTLE ARE IN POOR CONDITION



Picture of other deficiency: CLOSING DEVICES FOR THE DOOR OF CARGO HOLD VENTILATION ROOM ARE MISSING

