


## **Deficiency Photo of the Year - 2022**

Ship name:	ASIAN HARMONY
IMO Number:	9196486
Flag:	Panama
Call sign/MMSI	3E3364/352978262
Ship type:	General cargo/multipurpose ship
Date keel laid:	30.06.1998
Gross tonnage:	4,353
Recognized organization:	Nippon Kaiji Kyokai
ISM Company:	Dalian Wonder Ship Management Co., Ltd
	(IMO No. 6059679)
Port of inspection:	Shanghai, China
Date of inspection:	03.08.2022
Detention:	Yes




Nature of deficiency:	Pilot ladders and hoist/pilot transfer arrangements: Side rope of starboard side pilot ladder was broken on 29 July, 2022 during the embarkation of the pilot, which poses a danger for the embarkation/disembarkation of the pilot.
Reason for winning the prize:	This photo showed the dangerous condition of the pilot ladder.
Photo of detainable deficiency:	Yes
Picture of the ship	



<u>Picture of the same deficiency: Pilot ladders and hoist/pilot transfer arrangements</u>



Pictures of detainable deficiency: Isolation valve on fire main cannot be closed during testing the emergency fire pump



Picture of detainable deficiency: The flame failure alarm for the hot water boiler did not activate during the test



<u>Pictures of other deficiency: One manhole cover in the safety passage on the second deck of NO.1 cargo hold missing</u>



<u>Picture of other deficiency: The viewing screen of port side INMARSAT-C</u>
<u>station is not clear</u>



<u>Picture of other deficiency: There was no fire detector test tools onboard, and</u> the bottle of spraying agent for the smoke fire detector was empty

