




Deficiency Photo of the Year – 2013

Ship name:	VIENNE
IMO Number:	9362176
Flag:	Mongolia
Call sign/MMSI	JVRU4
Ship type:	Bulk carrier
Date keel laid:	28.09.2004
Gross tonnage:	1,266
Recognized organization:	Singclass International
ISM Company:	GRM Shipping Sdn Bhd (IMO No. 5473369)
Port of inspection:	Zamboanga, Philippines
Date of inspection:	09.07.2013
Detention:	Yes*



Nature of deficiency:	Water/Weathertight condition: Bulwarks and freeing ports-Deteriorated/Damaged /Corrosion.
Reason for winning the prize:	This picture provides the clear evidence of serious corrosion of the vessel.
Photo of detainable deficiency:	No

* Detention was warranted for reason of deficiencies of failure of radar and echo sounder, defective anchor windlass.

Pictures of the ship



Pictures of other deficiency: DETERORATION DUE TO CORROSION LEADS A HOLE



Picture of other deficiency: GASKET, CLOSING DEVICES DETERIORATED




Pictures of other deficiency: DEFORMATION, DAMAGED/
CRACKING/CORROSION OF VENTILATORS, AIR PIPES, CASINGS



Pictures of other deficiency: DETERIORATED VINYL FLOOR TILES, OILY
DECK



Pictures of other deficiency: OILY, UNNECESSARY ITEMS SCATTERED
ENGINE ROOM



Pictures of other deficiency: DETERIORATED/DAMAGED/CORROSION OF BULWARKS AND FREEING PORTS



Pictures other deficiency: OPEN/NOT SECURED ELECTRICAL WIRES HAZARD

