



Deficiency Photo of the Year – 2024

Ship name:	HC WAND
IMO Number:	9298430
Flag:	Togo
Call sign/MMSI	5VIG5/671311000
Ship type:	Bulk carrier
Date keel laid:	11.07.2003
Gross tonnage:	1,997
Recognized organization:	Cosmos Marine Bureau
ISM Company:	Alpha Shipping Ltd (IMO No. 0047768)
Port of inspection:	Busan, Republic of Korea
Date of inspection:	08.10.2024
Detention:	Yes



Nature of deficiency:	Cargo hold deck flooded - inner plate of cargo hold heavily corroded - bottom of cargo hold upper side of No.1 wbt(s) found several holes (total 11 spots).
Reason for winning the prize:	This picture catches the scene of flooding in the bottom of cargo hold from ballast tank.
Photo of detainable deficiency:	Yes

Picture of the ship



Picture of the same detainable deficiency: Cargo & other hatchways



Picture of other detainable deficiency: Inflatable liferafts not working properly
- interval of serviced date exceed 12 months (last service date: 06-2023) - fail
to launching inflatable liferaft because hydrostatic release unit not working.



Picture of other detainable deficiency: Rescue boat on boat-deck starboard side found hole on bottom.




Picture of other detainable deficiency: Pipe of fixed fire-extinguishing system (CO₂) for cargo hold cut and heavily corroded.



Picture of other detainable deficiency: Quantity of food not suitable for the intended voyage.



Picture of other detainable deficiency: Sanitary facilities unhygienic; equipment are missing and not functioning; washing machine in laundry room missing.



Picture of other detainable deficiency: Fire detection alarm system not working.

